
# *Vasa* båtdelar

| Recorded by | Date | Del/part | Fyndnummer |
|---|---|---|---|
| FELIX/ | 2004-8/25 | PLANK VINDA (J | 01330 |

## Fyndplats/location

| Däck/deck | Sida/side | Balk/beam | Kanonport/gunport |
|---|---|---|---|
| | | | |

## Material

| Träslag/wood type | Conversion |
|---|---|
| PINE V |   |
| Fiberriktning/grain | |
| STRAIGHT | |

## Dimensioner (millimeters)

| Längd/length | Bredd/width | Tjocklek/thickness | Diameter (Axle) |
|---|---|---|---|
| 1130 V | 215 V | 35 V | |

**Joinery** Carved piece of pine. Could be head end for a clinker plank. Fastenings along lower edge and up the front end. No flange (might have broken off) No moldings. No scarf table (eroded) lower edge is beveled. No lating cove. ✓

**Fastenings** Some iron nails. Fastened from outside only. ✓

**Coatings**

**Skador/damage** Front end and top edge might have broken off. Eft end eroded. Some surface erosion. ✓

**Reparationer/repairs**

**Kommentar/comments** Could be portside forward head end. Maybe garboard ✓

**Association**