


| Vasa båtdelar                          |   | Del/part  | Fyndnummer        |
|--|---|---|-------------------|
| Recorded by<br>FELIX                   | Date<br>2004-9/13   |   | 23636             |
| Fyndplats/location                     |   |   |                   |
| Däck/deck                              | Sida/side   | Balk/beam   | Kanonport/gunport |
| Material                               |   |   |                   |
| Träslag/wood type                      |   | Conversion  |                   |
| Fiberriktning/grain<br>GROWN CURVATURE |   |  |                   |
| Dimensioner (millimeters)              |   |   |                   |
| Längd/length<br>1160 ✓                 | Bredd/width<br>max 67 ✓   | Tjocklek/thickness<br>max 57 ✓  | Diameter (Axle)   |
| Joinery                                | Single piece. One end is leveled with dado cut out and fastening hole. Other end tapers. Notch cut or fastening hole that's been broken open. ✓ |   |                   |
| Fastenings                             | Might have more iron fastenings than are visible on this. ✓   |   |                   |
| Coatings                               |   |   |                   |
| Skador/damage                          | surface erosion. ✓  |   |                   |
| Reparationer/repairs                   |   |   |                   |
| Kommentar/comments                     | Covered in PEG → wood?, Conversion?<br>How nails?<br>Could be clamp or stringer ✓   |   |                   |
| Association                            |   |   |                   |