


19 JUN 2008 FMH

10923 Crane block

part a



8008 Halliard block, fore

Sheave slots sawn, ends carved/cleaned up w/ chisels + gouges

112 Hook block

Iron strap preserved, not conserved (not vase?)
shell ash?

hook has mousing hole at tip

copper + paper tags

8692 Bowline SWATCH BLOCK

all surfaces eroded, no original edges, small grooves on back side
OAK

Seems to be chamfered on edges

XXX03 Bitmark swatch block

Oak