
# *Vasa* båtdelar

| Recorded by | Date | Del/part | Fyndnummer |
|---|---|---|---|
| FELIX/ | 2004-9/15 | Knee | 02714 + 02715 ✓ |

## Fyndplats/location

| Däck/deck | Sida/side | Balk/beam | Kanonport/gunport |
|---|---|---|---|
| | | | |


## Material

| Träslag/wood type | Conversion |
|---|---|
| OAK ✓ |  |
| Fiberriktning/grain: CROOK ✓ | |

## Dimensioner (millimeters)

| Längd/length | Bredd/width | Tjocklek/thickness | Diameter (Axle) |
|---|---|---|---|
| SIDED 430 | together max 95 | max 58 | |

**Joinery** knee with notch cut out - maybe lumber hole - maybe to go around stringer
great wood selection
!!! Holdings along grain !!!




✓

**Fastenings** 6 nails total
2 of 16 mm treenail holes (might have caused the split) ✓

**Coatings** one covered in PEG (02714)
other (02715) in good condition ✓

**Skador/damage** Split in the middle, surface erosion, some breakage at the ends ✓

**Reparationer/repairs**

**Kommentar/comments** HOLDINGS ✓

**Association**